



227713

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
SUPERFUND DIVISION
77 WEST JACKSON BOULEVARD
CHICAGO, ILLINOIS 60604

Varosta
F&E

11/03

10/10/01

October 10, 2001

SE-5J

Ms Rosalind Hecim
President, SOAR
215 E. Chicago Avenue
Suite 2407
Chicago, Illinois 60611

Dear Ms Hecim:

This letter responds to your request, on behalf of SOAR, for items in U.S. Environmental Protection Agency (USEPA) files related to the Lindsay Light II sites in Streeterville. I apologize if these have not come as quickly as you might like since both of the assigned On-Scene Coordinators are on long-term assignments, our supervisor has been assisting in the New York City cleanup and our Public Affairs Community Involvement Coordinator has taken a job outside of the USEPA (The new Community Involvement Coordinator is Mike Joyce at [312] 353-5546). However, I have reviewed our files and believe the attached documents are what you are seeking. Where USEPA documents reference outside sources, these secondary documents can usually be found in our Records Center on the 7th floor of the Metcalf Building at 77 West Jackson Boulevard or can be obtained from the original source.

The following documents are enclosed

530 North Lake Shore Drive

- Comments on proposed Work Plan and Health and Safety Plan (8/2/01)
- STS response to comments on Work Plan and Health and Safety Plan (8/6/01)
- Letter from Richard Berggreen, STS Consultants (8/15/01)
- Response letter to Richard Berggreen, STS Consultants (9/4/01)
- NOTE: The contractor's report on soil sampling, dated August 28, 2001 has been reviewed and an EPA response is being prepared.

600 North Lake Shore Drive

- NOTE: The contractor's report on a 2nd round of soil sampling, dated August 7, 2001 was reviewed and an EPA response is being prepared.

341 East Ohio

- Review of Quality Assurance Project Plan (6/4/01)
- Review of Health and Safety Plan (7/3/01)
- Work Plan comments (7/11/01)
- Letter on gamma survey (8/17/01)
- Comments on responses on Work Plan (9/4/01)
- Letter approving Work Plan (9/12)
- The review of responses to comments on the QAPP are being reviewed and a response letter will be sent before work commences.

221 North Columbus Drive (Golf Course)

- NOTE: Data from one contractor has been received and reviewed. Data from the other contractor has been requested. A response will be prepared when both data sets have been reviewed.

Parcel 14 (River View Development)

- USEPA response letter on review of data reports (7/12/01)

160 East Illinois Street (Kieffer Building)

- Letter to Bain Environmental (7/27)
- Cover letter and review of radiological survey (9/17, 9/4)

DuSable Park

- Review of Kerr-McGee survey (8/7)

If you have any questions on these items, please feel free to call me at (312) 886-5026.

Sincerely,

Larry Jensen, CHP
Senior Health Physicist
Emergency Response Section #3